


Northwest Chapel Hill Study Area


March 7, 2007









••••• JPA: Joint Planning Area Zoning Districts








2005 Traffic Conditions














NC86 Pedestrian Study Recommendations – 1




NC 86/Martin Luther King Jr. Boulevard Corridor and Town-Wide Pedestrian Safety Evaluation Study



NC86 Pedestrian Study Recommendations – 2



NC 86/Martin Luther King Jr. Boulevard Corridor and Town-Wide Pedestrian Safety Evaluation Study



Possible Intersection Design



KEY to Improvements Shown*

- Construct ADA-compliant our bramps Provide pedestrian signals
- Stripe crosswalk
- Construct aldereals across differency Construct aldereals with 6' min. planting strip
- Provide median pocket
- 7. Construct stone retaining wall at back of walk
- Stripe bike lanes.


- Construct bus pullout
- Replace bench at buil stop
- Widen flouleyard at Intersection 12. Stripe 11' wide travel lanes
- 13. Construct raised median
- 14. Ner rose outb radius to 25 feet maximum

NC 86/Martin Luther King Jr. Boulevard Corridor and Town-Wide Pedestrian Safety Evaluation Study Lapper + Marcons, PA sactioners accomment


Illustration 2: Typical Intersection

^{*} Not all improvements shown in each litustration


Possible Martin Luther King Jr. Blvd. Design




Timberlyne Community Mobility Assessment





Timberlyne Pedestrian Mobility Audit Area Results Sidewalk Coverage Ratings Februrary, 2007





Weaver Dairy Ext. Transit Options












Weaver Dairy Rd. Improvements – 1



Weaver Dairy Rd. Improvements – 2

