



Photo 1 – Looking toward side drainage ditch along a drainage swale in Ms. Brown’s yard. Arrow indicates direction of drainage. Roof drain lines from homes at 412 and 410 Simerville Rd come in from right, just past the natural area.



Photo 2 – Arrow indicates location of roof drain lines from 412 and 410 Simerville Rd, across Ms. Brown’s property.



Photo 3 – Roof drain outlets from 412 and 410 Simerville Rd at side drainage ditch.



Photo 4 – Closer view of outlets



Photo 5 – Roof drain outlet from 408 Simerville Rd home.



Photo 6 – Closer view of outlet



Photo 7 – Looking “upstream” along side drainage ditch on private property.



Photo 8 – Yard inlet at terminus of side drainage ditch