### Timberlyne **PEDESTRIAN/BICYCLE MOBILITY STUDY Results** Februrary 26, 2007 Go! Chapel Hill For a healthier more active life

### Timberlyne Activity Survey Results -February 2007 Mail Survey Page 1 of 3

### Go! Chapel Hil

Respondent Total = 107

		YES	NO	No Answer
	Do you Believe that physical activity is important?	75%	0%	25%
	Do you participate in 30 minutes of physical activity daily?	54%	20%	26%
4.a	Do you use public transit regularly?	23%	71%	6%

		At Least Once per Day	At Least Once per	At Least Once per Month	At Least Every 3 Months	At Least Once Per Year	Never	No Answer
1.a	I walk/bike through the neighborhood	52%	36%	7%	4%	1%	0%	0%
2.a	I walk/bike to Timberlyne Shopping Center	15%	49%	22%	10%	2%	0%	2%
3.a	I walk/bike to Chapel Hill North	0%	11%	14%	7%	14%	44%	10%

		MORE	LESS	NO CHANGE	No Answer
1.b	If there were better pedestrian/bicycle facilities in the neighborhood, I would walk/bike	68%	0%	32%	0%
2.b	If there were better pedestrian/bicycle facilities TO Timberlyne Shopping Center, I would walk/bike	64%	0%	36%	0%
3.b	If there were better pedestrian/bicycle facilities TO Chapel Hill North, I would walk/bike	78%	0%	19%	4%

If there were better pedestrian/bicycle facilities WITHIN <i>Timberlyne Shopping Center</i> , I would walk/bike	49%	1%	47%	3%
If there were better pedestrian/bicycle facilities WITHIN <i>Chapel Hill North</i> , I would walk/bike	53%	0%	39%	4%

	Leisure		Shopping	Excersize	Bus/Vanpool
2.d Why do you walk to <i>Timberlyne Shopping Center</i> ?	79%	64%	88%	7%	2%
3.d Why do you walk to <i>Chapel Hill North</i> ?	29%	8%	46%	3%	0%

Timberlyne Activity Survey Results - February 2007 Mail Survey Page 2 of 3	Distance to Bus Stop	Pedestrian Facilties Getting to Bus Stop	Lack of Facilities at Bus Stop	l have a Car	Schedule Issues	Route Access Issues	l think TTA is Unsafe	Travel Distance to Far
What are the major barriers to using public4.btransit in your neighborhood?	14%	15%	16%	3%	17%	5%	1%	2%


l have a Time Constrained Schedule	
7%	

5.a	How many minutes does your commute to work take?	See Chart Below
5.b	On a typical weekday, record minutes of travel time for each listed mode.	See Chart Below

		Crime	Fast Moving Traffic	Noise	Exhaust Fumes	Destinations Too Far	Inconsistent Sidewalk Coverage	Poor Lighting	No Bike Lanes	9
6	What are the major barriers to walking/ bicycling in your neighborhood?	7%	62%	3%	6%	11%	68%	35%	4%	

Time	Careless Drivers	Streets Too Narrow	MLK Blvd.	Hilly	Narrow Sidewalk Buffer
2%	4%	1%	2%	1%	2%


		Walking Club	Bicycling Club	Gardening Club	Running Club	Moms/ Parents Club	Flying Cclub	Dinner Club	Crafts Club	
7	If there were the following organizations in your neighborhood, would you participate?	36%	15%	23%	2%	2%	1%	1%	1%	ATTA




### How Many Minutes Does Your Commute To Work Take?


### Timberlyne Activity Survey Results -February 2007 Mail Survey Page 3 of 3


**Recorded Minutes of Travel Time per Transportation Mode** 






Februrary, 2007 Sidewalk Coverage Ratings Timberlyne Pedestrian Mobility Audit Area Results






Februrary, 2007 Roads with Sidewalk Coverage Timberlyne Pedestrian Mobility Audit Area Results



### **Pedestrian Experience**



## Timberlyne Study Area: Summary of Problem Streets 14

person cited this location as a problem. the segments that are requested for attention by residents. Highlighted segments indicates that more than one In addition to the audit results certain problem areas were identified by residents. Table 1 shows a summary of

need for better stripping, and color reflecting material on streets. General comments included lack of lighting throughout neighborhood, presence/visibility of speed limit signs,

Just Unsafe, no sidewalk, no crosswalk         Safety walking, speeding cars, school bus stop Poison Ivy on east side Crossing street, dangerous curve, wide road No curb ramp, crossing difficult, no sidewalk west side         Major pedestrian connector, dangerous curb, Postperson hit in the past.         Speeding traffic, stop sign running, curvy, no lines at intersections         School Bus Stop, visibility of speed limit signs, stop sign running, major pedestrian connector Pavement different textures, blind crest in hill for fast traffic         Pathway behind is TLC land, Dumping ground.         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         Dangerous to cross MLK	Segment     I	Segment         Problem         Suggestions by residents           1         Crossing Weaver Dairy         -Crosswalk across Weaver I           -Crosswalk at Bank Drive,         -Crosswalk at Bank Drive,	re Suggested for Attention Suggestions by residents -Crosswalk across Weaver Dairy at entrance to trailer park -Crosswalk at Bank Drive,
Safety walking, speeding         cars, school bus stop         Poison Ivy on east side         Crossing street, dangerous         curve, wide road         No curb ramp, crossing         difficult, no sidewalk west         side         Major pedestrian connector,         dangerous curb, Postperson         hit in the past.         Speeding traffic, stop sign         running, curvy, no lines at         intersections         School Bus Stop, visibility         of speed limit signs,         stop sign running, major         pedestrian connector         Patwement different textures,         blind crest in hill for fast         traffic         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         No crossing         Cracks on sidewalk         Crossing         On crossing         Pedestrian Crossing         And, Dumping ground.         Cracks on sidewalk         Crossing         Pedestrian Crossing         Pangerous to cross MLK	2	Just Unsafe, no sidewalk, no crosswalk	-crosswalk from Timberlyne Road across Weaver
Poison Ivy on east side         Crossing street, dangerous         No curb ramp, crossing         difficult, no sidewalk west         side         Major pedestrian connector,         dangerous curb, Postperson         hit in the past.         Speeding traffic, stop sign         running, curvy, no lines at         intersections         School Bus Stop, visibility         of speed limit signs,         stop sign running, major         pedestrian connector         Pavement different textures,         blind crest in hill for fast         traffic         Speed limit sign         Speed limit sign         Pathway behind is TLC         land, Dumping ground.         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         Dangerous to cross MLK	3	Safety walking, speeding cars, school bus stop	
curve, wide road         No curb ramp, crossing         difficult, no sidewalk west         side         Major pedestrian connector,         dangerous curb, Postperson         hit in the past.         Speeding traffic, stop sign         running, curvy, no lines at         intersections         School Bus Stop, visibility         of speed limit signs,         stop sign running, major         pedestrian connector         Pavement different textures,         blind crest in hill for fast         traffic         Pathway behind is TLC         land, Dumping ground.         Cracks on sidewalk         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Crossing         Dangerous to cross MLK	6 9	Poison Ivy on east side Crossing street, dangerous	-Sidewalk on both sides of street
Major pedestrian connector, dangerous curb, Postperson hit in the past.Speeding traffic, stop sign running, curvy, no lines at intersections School Bus Stop, visibility of speed limit signs, stop sign running, major pedestrian connector Pavement different textures, blind crest in hill for fast trafficSpeed limit sign Pathway behind is TLC land, Dumping ground.Pathway behind is TLC land, Dumping ground.Cracks on sidewalk Cracks on sidewalkStop Line Not Painted No crosswalkStop line, Pedestrian Crossing Dangerous to cross MLK	10	No curb ramp, crossing difficult, no sidewalk west side	-Curb ramp at Kingston Drive
Speeding traffic, stop sign running, curvy, no lines at intersections School Bus Stop, visibility of speed limit signs, stop sign running, major pedestrian connector Pavement different textures, blind crest in hill for fast trafficSpeed limit signSpeed limit signSpeed limit signCracks on sidewalkStop Line Not Painted No crosswalkStop line, Pedestrian CrossingCrossing Dangerous to cross MLK	=	Major pedestrian connector, dangerous curb, Postperson hit in the past.	-sidewalk on both sides -crosswalk at Silver Cedar/Kingston inter -crosswalk at Shopping Center Driveway building -enhanced entrance behind Timberlyne
School Bus Stop, visibility of speed limit signs, stop sign running, major pedestrian connector Pavement different textures, blind crest in hill for fast trafficSpeed limit signSpeed limit signPathway behind is TLC land, Dumping ground.Cracks on sidewalk Cracks on sidewalkStop Line Not Painted No crosswalkStop line, Pedestrian CrossingCrossing Dangerous to cross MLK	17	Speeding traffic, stop sign running, curvy, no lines at intersections	-Posted "Narrow and Curvy Road"
Pavement different textures, blind crest in hill for fast traffic         Speed limit sign         Pathway behind is TLC         land, Dumping ground.         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         Dangerous to cross MLK	19	School Bus Stop, visibility of speed limit signs, stop sign running, major pedestrian connector	-Crosswalk or raised crosswalk needed at and Kingston, -check speed limit signs for visibility, -Install sidewalk
Speed limit sign         Pathway behind is TLC         land, Dumping ground.         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         Dangerous to cross MLK	20	Pavement different textures, blind crest in hill for fast traffic	-Smooth out pavement -Vehicle caution signs -no outlet sign on Blackcherry Lane off o
Pathway behind is TLC         land, Dumping ground.         Cracks on sidewalk         Stop Line Not Painted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         Dangerous to cross MLK	26	Speed limit sign	-Install sidewalk, -Check speed limit signs
Cracks on sidewalkStop Line Not PaintedNo crosswalkCracks on sidewalkStop line, PedestrianCrossingPedestrian CrossingDangerous to cross MLK	28	Pathway behind is TLC land, Dumping ground.	
Stop Line Not Fainted         No crosswalk         Cracks on sidewalk         Stop line, Pedestrian         Crossing         61         Pedestrian Crossing         Dangerous to cross MLK	33	Cracks on sidewalk	7
Cracks on sidewalk Stop line, Pedestrian Crossing 61 Pedestrian Crossing Dangerous to cross MLK	<u>51</u>	Stop Line Not Painted No crosswalk	Paint stop line
61 Pedestrian Crossing Dangerous to cross MLK	<u>60</u>	Cracks on sidewalk Stop line, Pedestrian	Paint stop line
	<u>60 @ 61</u> 63	Pedestrian Crossing Dangerous to cross MLK	

# Table 1: Summary of Segments that are Suggested for Attention