

Possible Landscape Improvements Adjacent to NCDOT Streets

Fordham Boulevard

	Location	ROW	Constraints	<u>Plants</u>	Approval
1)	I-40 Intersection (northside)	Yes	OH utilities, signage, some drainage issues, existing plants	50 large, 80 small, large daylily beds	Medium- Easy (*)
2)	I-40 to Erwin Road (center median)	Yes	Center drainage swale, turnlanes NCDOT approval previously denied	60 small, extensive hedges	Difficult
3)	Erwin Intesection (Dobbins median)	Yes	Old road bed, likely utilities	5 large, 10 small	Medium- easy (*)
4)	Franklin Street Split (large center median)	Yes	Existing pear trees, difficult maintenance access, wet site	30 large, 50 small	Easy (*)
. 5)	Mc Donalds (service road median)	Yes	OH utilities, parking, compacted soil, bank and swale, setbacks	15 small	Medium
6)	Foxcroft to Franklin (service road median)	Yes	OH utilities, center swale, setbacks	20 small	Medium- difficult
7)	Rams Plaza (large center median)	Yes	Drainage swale, difficult maintenance access	5 large, 15 small	Medium- easy (*)
8)	Eastgate (service road median)	Yes	OH utilities, center swale, sewer, no C&G, setbacks	20 small	Difficult
9)	Eastgate (center median)	Yes	Center swale, limited C&G, setbacks	20 smali	Difficult
10)	Holiday Inn	Yes/no	OH utilities, swale, owner approval	5 small	Medium- difficult
11)	Burger King	No	Major sewer lines, owner approval	15 small	Medium- difficult
12)	University Mall	No	Limited space, commercial visibility, owner approval	10 large	Medium- difficult
13)	Estes to Carrboro (center median infill)	Yes		50 small and/or extensive hedges	Medium
14)	Christopher Road (median)	Yes	Water line, setbacks, limited C&G		Medium- difficult



15) NC 54 (intersection quads	Yes s)	Existing vegetation, drainage	10 large, 20 small, daylily beds	Easy (*)
16) Highland Woods (median)	Yes	Limited space, drainage swale	5 large, 5 small	Medium- easy (*)
17) South Columbia (intersection quads	Yes)	Work around existing trees, view of Merritt's pasture	50 small, daylily beds	Easy (*)
18) South Columbia (E-way marker)	Yes/no	Remove existing pears, limited space	10 small, daylily beds	Easy (*)
		NC 54		
Location	ROW	Constraints	<u>Plants</u>	Approval
19) E-way marker	Yes	Existing Durham County plantings, steep slope	20 small, very large daylily bed	Medium- easy (*)
20) Barbee Chapel Roa (service road media		Existing Durham County plantings, OH utilities, swale	10 large, 20 small	Medium
21) University Inn (center median)	Yes	Limited C&G, limited space, setbacks, signs	15 small and/or hedges	Medium- difficult
22) UNC Administration (center median)	Yes	Very limited space, setbacks	10 small and/or hedges	Difficult
		Franklin Street		
Location	ROW	<u>Constraints</u>	<u>Plants</u>	<u>Approval</u>
23) WCHL	No	Sewer line, slope, drainage, owner approval	10 small	Medium
24) Etna to Sienna	No	OH utilities, existing plantings, owner approval	5 small	Medium
25) Collier Cobb	No	OH utilities, existing plantings, owner approval	2 small	Medium
26) Photoquick	Yes/no	OH utilities, existing plantings, owner approval	2 small	Medium
27) Star of India	No	OH utilities, owner approval	2 small	Medium



			.6			
28)	Plant Road to Howell (southside)	Yes/no	Steep slopes, vines, owner approval	15 small	Medium- easy (*)	
29)	Danzinger property	Town	Very steep slopes, OH utilities	10 small	Easy (*)	
30)	Elizabeth Street	No	Owner approval	2 large	Medium	
Airport Road						
	Location	ROW	Constraints	<u>Plants</u>	Approval	
31)	I-40 to Homestead (center median)	Yes	Setbacks, limited space	Under study, mix of small trees & hedges	Medium- easy (*)	
32)	I-40 to Homestead (outer edges)	Yes/no	OH utilities, limited space, some steep slopes	Under study	Medium- easy (*)	
33)	Duke Power	No	Utilities likely, existing plants	5 large, 15 small	Medium	
34)	Homestead (old gas station)	No	Limited space, site triangles, redevelopment likely	5 small	Medium	
35)	Horan's Hardware	No	Limited space, owner approval, redevelopment likely	2 small	Medium	
36)	Public Works (Fran repair)	UNC	Competing trees and vines, some drainage problems	10 iarge, 10 small	Easy (*)	
37)	UNC Physical Plant (Fran repair)	UNC	Competing trees and vines, OH utilities, steep slopes	10 large	Medium- Easy (*)	
38)	YMCA	No	OH utilities, limited space existing vegetation	5 small	Medium- easy (*)	

39) Sharon Heights

40) Sav-A-Center

No

No

OH utilities, some steep slopes,

Gas line, exposed rock, owner

previously denied approval

owner approval

5 large, 10 Small

5 large

Medium

Difficult